

Measurements

Take all the other measures as usually (see our measuring instructions). Remember to use the belt on the waist and please note the N-point (neck point) and Q-point. To help measuring you can mark the N-point and Q-point with a piece tape.

Pay attention to following extra measures for para-shooting jackets:

4. Widest circumference at hip area

Measure widest circumference on the hip area. See measure 4 in the picture.

12a. Back length from N-point to seat

Measure from the highest point of the shoulder from N-point to the back over the waist to the seat.

12b. Front length from N-point to thigh


Measure from the highest point of the shoulder from N-point along the front side to thigh.

12c. Back & front length (total) from seat over N-point to thigh

Measure from the seat over the N-point, continue measuring along the front side to the thigh.

If the shooter has an asymmetrical body structure please take measures 5-10 on both right and left side.

The measures are not measures of a readymade jacket but of the shooter. Do not add or deduct anything.

**Important**

We produce para-shooting jackets only in KT Prime and X.9 models (iCanvas, Hybrid and Canvas) to guarantee the best possible fitting. Jackets are made as normal ISSF jackets (same stiffness, same materials and same overlap) except for the length. If the shooter has any special requests for example regarding the materials or because of local rules or rules interpretations please inform us when ordering. Changes and repairs caused by lack of information provided to us are not covered by our guarantee.

Photos

With every made to measure order we need six photos of the shooter:

- Front, profile and back (shooter sitting straight)
- Front, profile and back (shooter in shooting position)
- Extra photos if the shooter has several different shooting positions.